5/46

24688 Work Order: DART AEROSPACE LTD D3162-041 Part Number: Description: Bracket assembly. Stack of 7 Drawing: D3162 Rev. K & Qty:

	P# 04.11.29		54 ·	,	
Step	Location	Procedure	By	Date	Qty
1	EXPEDITING	Issue Work Order	4	05.10.26	30
2	METAL / CNC-CELL	Cut Blanks. Blank size: 1.150" x 0.985" x .063" thick. Grain along .985 Matl: 6061-T6 .063" thick (M6061T6S.063)			2
3	HAAS	Machine as per Folio FA239 Stack of 7	ナル	05.11.12	30
3	11243	Batch MISS 6	スト	05.11.12	30
4	QC	Inspect Level 2	コ.ト	05-11-12	30
5	QC	Inspect Level 8	me	odulis	30
6	METAL / CNC-CELL	Deburr break all unmarked sharp edges .005 to 0.010	SAD	05/11/13	30
7 A	METAL	Form as per drawing	SB	05/11/14	30
78	GA	C'sink holes as per Dug D3162 Chemical conversion coat as per QSI 005 4.1	FF	05/11/15	30
8	FINISHING	Chemical conversion coat as per QSI 005 4.1	FF	05/11/15	30
9	STORES	Pick: Oty Part Number Description MS21059L3 Nutplate M12240 MS20426AD3-4 Rivet M15786	FF	05/11/15	30
10	METAL	Assemble as per drawing	FF	05/11/15	30
11	QC	Inspect Level 5	7	05-11-16	30
12	STORES	Identify and stock with PIN+ BIN using fine point perminent		05/11/16	30 (
13	EXPEDITING	Close W/O Inspect level 21 Cost/part 2/3 Sur os/II/21 (30)	Q	० जी प्रीस	30

	Rev	Date	Change	Revised By	Approved
	Α	02.05.14	New Issue .	NG	CE, 2002/5/2002
	Al	03.03.20	Added c'sink	1	4
-					71

3,05

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES								
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector			
		·								

Part No:	PAR #:	Fault Category:	NCR: Yes No	DQA:	Date: <u>Ć</u>	<u> </u>
			QA: N/C C	losed:	Date: _	


NCR:		WORK ORDER NON-CONFORMANCE (NCR)										
		Description of NC		Corrective Action Section B	Verification							
DATE	STEP	Section A	Initial Chief Eng	Action Description Sign Chief Eng Date	Section C	Approval Chief Eng	Approval QC inspector					
							,					
							Ė					
						-	-					
							-					
		·										

NOTE: Date & initial all entries






			The state of the s	
DESIG	**	DRAWN BY	DART AEROSPAC HAWKESBURY, ONTARIO,	
CHEC	KED al	APPROVED	DRAWING NO.	REV. B
		 -	D3162	SHEET 1 OF 1
DATE	13		TITLE	SCALE
04.1	10.18		BRACKET ASSEMBLY	1:1
 Α		02.04.30	NEW ISSUE	
В		04.10.18	ADD PART MARKING	



D3162-1 BRACKET FLAT PATTERN



D3162-041 BRACKET ASSEMBLY

WORK OF

NOTES:

1) MATERIAL: 6061-T6 (QQ-A-250/11) 0.063 THICK (REF. DART SPEC. M6061T6S.063)
2) FINISH: CHEMICAL CONVERSION COAT PER DART QSI 005 4.1
3) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED

BREAK EDGES 0.005 TO 0.010

ALL DIMENSIONS ARE IN INCHES

IDENTIFY WITH DART P/N USING FINE POINT PERMANENT INK MARKER

Copyright © 2002 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

Job Costing Report

Dart Aerospace Ltd. Hawkesbury

Oct 25, 2005 04:04 pm

: 0024688 Work Order No

Project Name : D3162-041 Project For : WK546

Work Order Type : Main Main WO Number :

House Part Number: D3162-041 Description : Bracket Assembly

Manufactured : Yes

Amount Req'd: 30 Amount Done : 0

: 10-25-05 Start Date

Est Finish Date : 11-15-05 Act Finish Date :

Drawings Reqd : No

Approval Rec'd :

Ok for Approval :

Department Code:

Burden Flags : NNNNNN

WO Status : Open

Invoice State : Not Invoiced

Invoice Date :

Invoice Number : Invoice Amount : 0.00

Order Entry No :

OE Value : 0.00

Est Mark Up : 0.000% Actual Mark Up : 0.000%

\$0 Posted to Finished Goods

•		Estimated	Actual	Var. %	Posted	To Post
_======================================	==:	======================================		=======	===========	==========
Material Cost	:	0.00	0.00	0.00	0.00	0.00
Engineering Hours	:	0.00	0.00	0.00		3
Engineering Cost	:	0.00	0.00	0.00	0.00	, , , , , , , , , , , , , , , , , , ,
Production Hours	:	0.00	0.00	0.00		anthis a
Production Cost	:	0.00	0.00	0.00	0.00	0.00
Packaging Hours	:	0.00	0.00	0.00		
Packaging Cost	:	0.00	0.00	0.00	0.00	0.00
OverHead Hours	:	0.00	0.00	0.00		
OverHead Cost	:	0.00	0.00	0.00	0.00	0.00
CNC Hours	:	0.00	0.00	0.00		
CNC	:	0.00	0.00	0.00	0.00	0.00
Misc. Hours	:	0.00	0.00	0.00		
Misc.	:	0.00	0.00	0.00	0.00	0.00
**		========		======		
Burden	:	0.00	0.00	0.00		
		========	========	======		
Total Cost	:	0.00	0.00	0.00		
Mark up	•	0.000	0.000			
Selling Cost	:	0.00	0.00			
2011119 0000	•	0.00	0.00			

		Estimated		Actual
Labour Hrs/Amount Done	:	0.00		0.00
Profits/(Loss)	:	0.00	•	0.00

DART AERO	SPACE LTD			\	Work Order:	24688
Description: t	racket assen		Part Number:	D 3/62-041		
Inspection Dwg	1 /33/62 Rev:	В				Page 1 of 1
	FIRST	ARTICLE IN	SPECTION	ON CHE	CKLIST	
	X	First Artic		Proto		
Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
688	+ .010	-688				
0.250	4-005	.253	//			
- 226	±-010	.226	/			
. 200	÷ .010	-195				,
1.062	+ -010	-062				
.500	+ .010	- 499				
. 294	+ .010	.294	<i>*</i>	-X		···
Ø.098	+-004 001 +-010	./01		·-A'		
.954	010	.953			*	
190 × 100°	+	109				
1.09	+ .030	1-09				
- 544 - 344	± -010	. <u>540</u> . 343				
2771	010	- 313				
	vi					<u> </u>
				<u> </u>		
eministration of the same of t						3
		1				
to the second se	i		· ·			
		1				
THE MALE CONTROL IN THE CONTROL OF T						
						187
		;	1			

				•	
Measured by:	J.L	Audited by:	me	Prototype Approval:	
Date:	05.11.12	Date:	05/11/12	Date:	

Rev	Date "	Change	Revised by	Approved	
A		l-New Issue	KJ/RF		

Date

Thursday, 11/17/2005 6:01:39 PM

User:

Linda Lacelle

Process Sheet

Drawing Name

Part Number

Due Date

Drawing Number

Project Number

Customer

: CU-DAR001 Dart Helicopters Services

: 24688 Job Number : 10688

Estimate Number

P.O. Number

: 11/17/2005 This Issue

: NC

Prsht Rev.

: 11 First Issue

Previous Run

Written By Checked & Approved By

Comment

Type

; Est

S.O. No. :

: MACHINED PARTS

02.05.14 New Issue NG

Drawing Revision Material

: 11/24/2005

: B

: D3162041

: D3162 REV B

: BRACKET ASSEMBLY

Qty:

30 Um:

Each

Additional Product

Job Number:



Machine Or Operation: Seq. #:

M6061T6S063 1.0

2.0 BAND SAW

Description:

6061-T6 .063 Sheet BAND SAW

Comment: BAND SAW

Cut Blanks.Blank size: 1.150" x 0.985" x .063" thick. Grain along .985

3.0

HAAS1



Comment: HAAS CNC VERTICAL MACHINING #1

Machine as per Folio FA239 Stack of 7

HAAS CNC VERTICAL MACHINING #1

Batch_

4.0

INSPECT PARTS AS THEY COME OFF MACHINE



Comment: INSPECT PARTS AS THEY COME OFF MACHINE

5.0

QC8

QC2

SECOND CHECK

Comment: SECOND CHECK

6.0

SMALL FAB 1

SMALL & MEDIUM FAB RESOURCE 1





Comment: SMALL & MEDIUM FAB RESOURCE 1

Deburr break all unmarked sharp edges .005 to 0.010

Form as per drawing

C'sink holes as per Dwg D3162

Date: User: Thursday, 11/17/2005 6:01:39 PM

Linda Lacelle

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: BRACKET ASSEMBLY

Job Number: 24688

Part Number: D3162041

Job Number:



Seq. #:

Machine Or Operation:

Description:

7.0

HAND FINISHING1

HAND FINISHING RESOURCE #1





Comment: HAND FINISHING RESOURCE #1

Chemical Conversion Coat as per QSI 005 4.1

MS21059L3 8.0

Nut Plate

MS20426AD34 9.0

RIVET

10.0

SMALL FAB 1

SMALL & MEDIUM FAB RESOURCE 1



Comment: SMALL & MEDIUM FAB RESOURCE 1

Assemble as per drawing

11.0

QC5

INSPECT WORK TO CURRENT STEP



Comment: INSPECT WORK TO CURRENT STEP

12.0

PACKAGING

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

Identify with P/N and B/N using a permanent fine point marker, then Stock

Location:

13.0

DC

DOCUMENT CONTROL



Comment: DOCUMENT CONTROL

Inspection Level 21

Job Completion

